



## Steps of TK series manually installing USB driver


1. Right-click My Computer on the desktop, and select [Manage] in the pop-up right-click menu. As shown below:




2. Find the “device manager” option in the pop-up computer management window, as shown in the figure below:





3. Find the unrecognized USB serial port in the device manager, right-click the serial port and select [Update Driver], as shown in the figure below.




4. In the pop-up dialog box, select “Browse my computer for find driver software”, as shown in the figure below:



5. In the pop-up dialog box, select the [Browse] button to select the folder where the driver is located. The general choice is "C:\Program Files (x86)\CM\mView 1.38.02\usb driver". Check [Include subfolders], as shown below:





6. Click the [Next] button to start the USB driver installation.

7. The installation is complete as shown in the figure below:

